

Location Map (Beverly Park Floodplain Connection)





Figure 1: Aerial view of concrete channel in Beverly Park neighborhood



Figure 2: Concrete channel discharging into North Fork of Kent Creek. Broken concrete and debris are present.



Figure 3: Concrete channel passing under Gilbert Avenue. Invasive brush impedes flow.